


3. Contact the AC wire to power system, connect black cable to L, connect white cable to N, connect green cable to grounding.

Accessories



4. Tighten 6 x screws between arm and junction box, turn

