










Selection chart Accessories for Barcode Bluetooth Hand-held scanner BCS 160^{ex} BT

Illustration	Description	➔ Order no.
	<p>Ex base station for use in Ex area Zone 1/21</p> <ul style="list-style-type: none"> ■ RS232/RS422 or USB-interface ■ without connection cable ■ Installation in hazardous area ■ Power supply via power supply module Type 17-21BB-170x 	17-21BB-1707/0000
	<p>Connection cable</p> <ul style="list-style-type: none"> ■ RJ45 to Ex-base station ■ assembled with 4 pin plug to power pack 	
	<ul style="list-style-type: none"> - Scanner cable, RS232, plane, 1.8 m 	03-9828-0044
	<ul style="list-style-type: none"> - Scanner cable, RS232, spiral, 3.8 m 	03-9828-0045
	<ul style="list-style-type: none"> - Scanner cable, USB, plane, 1.8 m 	03-9828-0046
	<ul style="list-style-type: none"> - Scanner cable, USB, spiral, 3.8 m 	03-9828-0047
	<p>Non Ex base station</p> <ul style="list-style-type: none"> ■ RS232 or USB-interface ■ without connection cable and power supply ■ Installation outside hazardous area 	03-9849-0063
	<p>Power supply for non Ex-base station and charging station</p> <ul style="list-style-type: none"> ■ use only outside of hazardous area ■ Input: AC 90 to 250 V/Output: DC 5 V 	03-9911-0039
	<p>Connection cable</p> <ul style="list-style-type: none"> ■ RJ45 to non Ex-base station ■ assembled for connection to RS232 or USB interface 	
	<ul style="list-style-type: none"> - Scanner cable, RS232, plane, 1.8 m 	03-9828-0040
	<ul style="list-style-type: none"> - Scanner cable, RS232, spiral, 3.8 m 	03-9828-0041
	<ul style="list-style-type: none"> - Scanner cable, USB, plane, 1.8 m 	03-9828-0042
	<ul style="list-style-type: none"> - Scanner cable, USB, spiral, 3.8 m 	03-9828-0043
	<p>Non Ex charging station</p> <ul style="list-style-type: none"> ■ Charging only outside of hazardous area ■ without power supply ■ for charging the BCS 160^{ex} BT 	03-9849-0064
	<p>Power supply for non Ex-base station and charging station</p> <ul style="list-style-type: none"> ■ use only outside of hazardous area ■ Input: AC 90 to 250 V/Output: DC 5 V 	03-9911-0039

Selection chart Accessories for Barcode Bluetooth Hand-held scanner BCS 160^{ex} BT

Illustration	Description	➔ Order no.
	Spare battery <ul style="list-style-type: none">■ explosion proofed version■ 3.6 V/2250 mAh Li-Ion	17-21BE-M040/0000
	Connection cable to following systems: <ul style="list-style-type: none">■ POLARIS power modul■ Power pack of BCS 302^{ex} Type 17-21BB-0217 bis 17-21BB-0220■ Power pack of BCS 3800^{ex} Type 17-21BB-1700 bis 17-21BB-1702■ RJ45 to BCS 160^{ex} hand-held scanner■ assembled with 4 pin plug to power pack<ul style="list-style-type: none">- Scanner cable, RS232, plane, 1.8 m- Scanner cable, RS232, plane, 1.8 m	17-21BE-M020/0000 17-21BE-M030/0000
	Desk holder	03-9849-0065
	Tripod holder	03-9849-0066